



**LONE STAR INDUSTRIES, INC.**

Utah Division

Date: what's required here  
LPS S-26

FILE W/045/021

**RECEIVED**  
MAY 26 1987

DIVISION OF  
OIL, GAS & MINING

P.O. Box 1469  
Salt Lake City, Utah 84110  
801-328-4891

May 19, 1987

Mr. L. P. Braxton  
Administrator  
Mineral Resource Development and  
Reclamation Program  
355 W. North Temple  
3 Triad Center, Suite 350  
Salt Lake City, UT 84180-1203

Dear Mr. Braxton:

This letter is in response to your comment on the diversion channel discussed in question No. 24. We will line the entire length of the channel with a 3" minus material before the 8" - 15" rip-rap is put in place.

If you have any questions please advise.

Sincerely,

James R. Lake  
Mine Superintendent

JRL:cj

cc: T. Saunders  
D. Vu  
R. Kronstadt